Test Report No. : USA00025394
Report Date : April 2, 2019

TEST REPORT

Client: Brentano, Inc.
260 Holbrook Drive
Wheeling, IL 60090
Attention: Lan Chenh
E-Mail: lchenh@brentanofabrics.com

Sample Description as Declared :

Sample Description :	Upholstery Fabric
Color :	9638-05
Style # :	9638 Marseille, 9644 Calais, 9642 Loire, 9646 Seine
Po:	DES2448
Fabric/Garment Weight :	Not Provided
Fiber Content :	41% Viscose, 39% Linen, 20% Polyester
No. of Samples:	1
End Use :	Upholstery
Finish :	Not Provided
Sample Received Date :	March 28, 2019
Final Confirmation Received Date:	March 28, 2019
Report Completion Date :	April 2, 2019

For and on behalf of
Intertek Products Group North America:
Edwin Serrano

Intertek North America
545 E Algonquin Road, Suite F
Arlington Heights, Illinois 60005
Telephone: 847-871-1020 Fax: 847-439-6156

AT-1348

TEST RESULTS:

Style # : 9638 Marseille, 9644 Calais, 9642 Loire, 9646 Seine

CA TB 117:2013 – Smolder Resistance of Materials used in Upholstered Furniture
-Section 1: Cover Fabric Test

Component Description: Upholstery Fabric; Color 9638-05			
Initial Test			
	Vertical Char length (Inches)	Mock-up specimen continues to smolder After 45 Minutes	Mock-up test specimen transitions to open flaming
Specimen 1	0.6	No	No
Specimen 2	0.7	No	No
Specimen 3	0.7	No	No

Requirements: A cover fabric material considered pass or fail based on following criteria

1. A single mock-up test specimen fails to meet the requirements of this test procedure if any of the following criteria occurs:

a) The mock-up test specimen continues to smolder after 45 minutes test duration.

b) A vertical Char length (measured as specified in step 11.9 of ASTM E1353-08a$^{\varepsilon 1}$) of more than 1.8 inches (45 mm) develops on the cover fabric.

c) The mock-up test specimen transitions to open flaming.

2 The cover fabric passes the test if three initial mock-up specimens pass the test, i.e., the cigarettes burn their full length and the mock-ups are no longer smoldering.

3 If more than one initial specimen fails, the cover fabric fails the test.

4 If any one of the three initial specimens fails, repeat the test on additional three specimens.

5 If all three additional specimens pass the test, the cover fabric passes the test. If any one of the additional three specimens fails, the cover fabric fails the test.

Note: For Cover fabrics that pass this section, the first layer of filling materials located below the cover fabric shall also meet the test requirements of section 3 of CA TB -117 :2013

Conclusion: The cover fabric material submitted does meet the flame resistance requirements when tested in accordance with the Bureau of Electronic & Appliance Repair Home Furnishings and Thermal Insulation, Technical Bulletin 117 – 2013, Section 1: Cover fabric test

Intertek North America
545 E Algonquin Road, Suite F
Arlington Heights, Illinois 60005
Telephone: 847-871-1020 Fax: 847-439-6156

ilac-MRA
ANAB ACCREDITED ISO/IEC 17025 TESTING LABORATORY AT-1348

Style # : 9638 Marseille, 9644 Calais, 9642 Loire, 9646 Seine

NFPA 260-2013 - Standard Methods of Test and Classification System for Cigarette Ignition Resistance of Components of Upholstered Furniture

The material submitted is an NFPA 260 Class I cover fabric when tested in accordance with NFPA 260, Fabric Classification Test Method.

Specimen #	Vertical Char Length (mm)
1	15
2	16
3	13

Classification:
Class 1 - This class includes all fabrics which exhibit a vertical char of less than 45 mm on each of the three replications when subjected to the fabric classification test of NFPA 260, Section 6.1.

AATCC 116:2013 – Colorfastness to Crocking: AATCC Crockmeter Method

Sample: Upholstery Fabric; Color 9638-05	
Original	
Dry	Wet
4.5	4.5

ASTM D3511/D3511M-16- Pilling Resistance and Other Related Surface Changes of Textile Fabrics: Brush Pilling Tester

Sample Condition: As Received
Running Time: 4 Minutes, then 2 Minutes.

Sample: Upholstery Fabric; Color 9638-05	
Average Grade:	1.5
Hairiness / Fuzziness	Moderate

Rating System

Grade 5, No Pilling
Grade 4, Slight Pilling
Grade 3, Moderate Pilling
Grade 2, Severe Pilling
Grade 1, Very Severe Pilling

Intertek North America
545 E Algonquin Road, Suite F
Arlington Heights, Illinois 60005
Telephone: 847-871-1020 Fax: 847-439-6156

ilac-MRA
ANAB ACCREDITED ISO/IEC 17025 TESTING LABORATORY AT-1348