


TEST REPORT

Client: Brentano, Inc.
260 Holbrook Drive
Wheeling, IL 60090
Attention: Lan chenh
E-Mail: Lchenh@brentanofabrics.com

Sample Description as Declared :

Sample Description : Upholstery fabric
Color : 6815-01 and testing sample brown
Style # : Journal 6815
Fabric/Garment Weight : Not Provided
Fiber Content : 100% Silicone Face; Overall: 56% Polyurethane, 40% Polyester, 4% Silicone
No. of Samples: 2
End Use : Upholstery
Care Instructions : Not Provided
Sample Received Date : April 15, 2022
Final Confirmation Received Date: April 18, 2022
Report Completion Date : April 22, 2022



**For and on behalf of
Intertek Products Group North America:**

Intertek North America

545 E Algonquin Road, Suite F
Arlington Heights, Illinois 60005
Telephone: 847-871-1020 Fax: 847-439-6156



TESTING LABORATORY

AT-1348

Test Performed As Requested by Client:

16 CFR 1640: Standard for the Flammability of Upholstered Furniture, CA TB 117: 2013 - Smolder Resistance of Materials Used in Upholstered Furniture

Section 1 – Cover Fabric Test

Sample Description: Journal 6815 01/Upholstery Fabric

Initial Test				
	Vertical Char Length (in)	Mock-up Specimen Continues to Smolder after 45 minutes	Mock-up Specimen Transitions to Open Flaming	Result
Specimen 1	0.4	No	No	Pass
Specimen 2	0.4	No	No	Pass
Specimen 3	0.3	No	No	Pass

Conclusion:

The Sample submitted for testing **Passes** the requirements in 16 CFR PART 1640.5 Standard For The Flammability of Upholstered Furniture, California Technical Bulletin 117-2013 Section 1: Cover Fabric Test

AATCC TM8:2016e – Colorfastness to Crocking: AATCC Crockmeter Method

Staining Evaluation Method: Gray Scale for Staining

Test Results:

Specimen/Sample	Original	
	Dry	Wet
Journal 6815 Brown	4.5	4.5

Intertek North America

545 E Algonquin Road, Suite F
Arlington Heights, Illinois 60005
Telephone: 847-871-1020 Fax: 847-439-6156



TESTING LABORATORY
AT-1348

The test results stated in this report relate only to the item(s) tested. This test report may not be reproduced except in full, without written approval of Intertek.

*If you need assistance in interpreting these results or if you have any questions,
please feel free to call Customer Service Department*

This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or willful misconduct.

Intertek North America

545 E Algonquin Road, Suite F
Arlington Heights, Illinois 60005
Telephone: 847-871-1020 Fax: 847-439-6156



AT-1348