


TEST REPORT

Client: Brentano
260 Holbrook Drive
Wheeling, IL 60090
Attention: Lan Chenh
E-Mail: Lchenh@brentanofabrics.com

Sample Description as Declared :

Sample Description : Upholstery fabric
Color : Testing Sample
Style # : 1350
Fabric/Garment Weight : Not Provided
Fiber Content : 35% Acrylic, 35% Polyester, 20% Viscose, 10% Cotton
No. of Samples: 1
End Use : Upholstery
Care Instructions : Follow Label on Product
Sample Received Date : June 27, 2022
Final Confirmation Received Date: June 27, 2022
Report Completion Date : June 30, 2022



**For and on behalf of
Intertek Products Group North America:**

Intertek North America

545 E Algonquin Road, Suite F
Arlington Heights, Illinois 60005
Telephone: 847-871-1020 Fax: 847-439-6156

Test Performed As Requested by Client:

**^16 CFR 1640: Standard for the Flammability of Upholstered Furniture, CA TB 117: 2013 - Smolder Resistance of Materials Used in Upholstered Furniture
Section 1 – Cover Fabric Test**

Sample Description: Upholstery Fabric - Style: 1350

Initial Test			
	Vertical Char Length (in)	Mock-up Specimen Continues to Smolder after 45 minutes	Mock-up Specimen Transitions to Open Flaming
Specimen 1	1.2	No	No
Specimen 2	0.7	No	No
Specimen 3	0.8	No	No

Conclusion:

The Sample submitted for testing **Passes** the requirements in 16 CFR PART 1640.5 Standard For The Flammability of Upholstered Furniture, California Technical Bulletin 117-2013 Section 1: Cover Fabric Test

“Report includes non-accredited test results. The test(s) marked with a carat (^) are not covered by our current ISO/IEC 17025:2017 scope of accreditation.”

The test results stated in this report relate only to the item(s) tested. This test report may not be reproduced except in full, without written approval of Intertek.



If you need assistance in interpreting these results or if you have any questions, please feel free to call Customer Service Department

This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or willful misconduct.

Intertek North America

545 E Algonquin Road, Suite F
Arlington Heights, Illinois 60005
Telephone: 847-871-1020 Fax: 847-439-6156